

NYLON RUNNER

Safety Recall Notice

Voluntary Product Recall of Nylon Runners Subject to Inspection



**18MM NYLON
RUNNER 60CM**
(All Colors)



**18MM NYLON
RUNNER 120CM**
(All Colors)

DIMENSIONS:

18mm wide and 60cm (24in) or 120cm (48in) long (length is measured when the runner is lying flat).

COLOR:

Solid colors: Red, Blue, Gold, Green, Gray, and Purple.



CE MARKING:

CE0333, found on the sewn-in label.

MANUFACTURING CODE:

2014 or 2015, found on the sewn-in label.

Salt Lake City, Utah (February 4, 2016) - Black Diamond Equipment, Ltd. in cooperation with the U.S. Consumer Product Safety Commission (CPSC), voluntarily issued a recall, subject to user inspection, of 18mm Nylon Runners 60cm/24in (Style Number 380060) and 18mm Nylon Runners 120cm/48in (Style Number 380061) because of a possibility that the Nylon Runner is not load-bearing and will fail under standard use.

This recall concerns nylon runners with a manufacturing code of 2014 or 2015, which is found on the sewn in label.

This recall is due to a small number of Nylon Runners found to contain a tape splice, resulting in a product that is not load-bearing and will fail under standard use.

No accidents have been reported; however, in the interest of customer safety, Black Diamond has decided to voluntarily issue a recall, subject to user inspection.

If you own Nylon Runners that fall within the scope of this recall, Black Diamond is requesting that you inspect them following the procedures outlined on the website below. If they fail inspection, stop use immediately and contact Black Diamond. We will replace your Nylon Runners free of charge.

For complete information about this recall go to:

BlackDiamondEquipment.com/runnerrecall

Contact information: Southern Approach PH: 0-800-335-000 | service@southernapproach.co.nz